

JUN 06 2005

10/623846 C of C



Practitioner's Docket No. J&R-1053

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Patent. No. : US 6,885,220 B2
Patentee : Bernhard Engl
Issued : Apr. 26, 2005
Art Unit : 2819
Examiner : Vibol Tan
Title : Current Source Circuit
Docket No. : J&R-1053
Customer No. : 24131

Certificate
JUN 14 2005
of Correction

Commissioner for Patents

P.O. Box 1450,
Alexandria, VA 22313-1450

ATTENTION: Decision and Certificate of Correction Branch of the Patent Issue Division

REQUEST FOR CERTIFICATE OF CORRECTION OF PATENT
FOR PTO MISTAKE (37 C.F.R.1.322(a))

1. Attached, in duplicate, is Form PTO-1050, with one copy suitable for printing.
2. The Document where the errors are shown correctly in the application file are:

Claim 3 appears correctly on page 4 of the Amendment filed on November 26, 2004 in the U.S. Patent and Trademark Office.

3. Please send the Certificate to:

Name : LERNER AND GREENBERG, P.A.
Address : P.O. BOX 2480, HOLLYWOOD, FL 33022-2480

Assignment recorded on _____


WERNER H. STEMBER
Name of authorized person signing
REG. NO. 34,956

Reel : _____
Frame : _____

Attorney of Record
Title of authorized person signing

Attached is a Recordal of assignment

Attached is a "CERTIFICATE UNDER 37 CFR 3.73(b)"
(establishing the right of the assignee to take action in this case)

Date: _____

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB Control Number.
(Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO : US 6,885,220 B2
ISSUED : Apr. 26, 2005
INVENTOR(S) : Bernhard Engl

It is certified that an error appears in the above-identified patent and that said Letters Patent are hereby corrected as shown below:

Column 7, line 62, claim 3 should read as follows:

terminals and emitter terminals, during operation of said

MAILING ADDRESS OF SENDER:

Lerner and Greenberg P.A.
P.O. Box 2480
Hollywood, FL 33020

PATENT NO. 6,885,220

No. of additional copies



Burden Hour Statement: This form is estimated to take 1.0 hour to complete. Time will vary upon the needs of the individual case. Any comments on the amount of time you are required to complete this form should be sent to the Chief Information Officer, Patent and Trademark Office, Washington, DC 20231. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Assistant Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO : US 6,885,220 B2
ISSUED : Apr. 26, 2005
INVENTOR(S) : Bernhard Engl

It is certified that an error appears in the above-identified patent and that said Letters Patent are hereby corrected as shown below:

Column 7, line 62, claim 3 should read as follows:

terminals and emitter terminals, during operation of said

MAILING ADDRESS OF SENDER:

Lerner and Greenberg P.A.
P.O. Box 2480
Hollywood, FL 33020

PATENT NO. 6,885,220

No. of additional copies



Burden Hour Statement: This form is estimated to take 1.0 hour to complete. Time will vary upon the needs of the individual case. Any comments on the amount of time you are required to complete this form should be sent to the Chief Information Officer, Patent and Trademark Office, Washington, DC 20231. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Assistant Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.